

Suggest a geological process which might have caused this.



Figure 1.1 A bus caught at an unusual angle when a road collapsed beneath it early in 1988 in the city of Norwich. The subsidence was due to failure of weathered chalk above old abandoned mines (Photo: Eastern Counties Newspapers).